

DDMP for the FY 2021-22

1. **Organizational Structure of your Organization**
Organization structure of office of the CEIA, Assam is enclosed as Annexed-I
2. **Photographs of various disasters occurred during the year (both man-made/natural) with details of occurrence.**
No such records are available within this period.
3. **Details of Electrical/Power Safety Training Conducted with Photographs.**
Does not arise.
4. **Mockdrill (if any conducted) with photographs and details.**
No such mockdrill programs organized by this Inspectorate.
5. **Photographs of Restoration works after occurrence of any disaster.**
Does not arise.
6. **Photographs of Customer Service Week conducted with details.**
Does not arise.
7. **Any Good practices/Safety measures adopted to minimize the effect of any disaster (Photographs and Technique).**
Periodic inspection as well as repeated instruction from this Inspectorate now the concern authority (APDCL) have been providing sophisticated fencings around the Public Distribution Sub-stations all over the Assam. Certainly this will minimize the electrical accident which were occurred from the unsafe Sub-station (Photograph enclosed).
8. **Tentative Action Plan for the FY 2022-23**
Enclosed as Annexed- III

Tentative Action Plan for the FY 2022-23

Sl. No.	Key Action	Implementation
1.	Awareness Programs on Electrical safety.	Office of the CEIA, Assam.
2.	Safety Inspection.	-Do-
3.	Distribution of electrical safety Circular for safe Electrical Installation.	-Do-
4.	Capacity Building of Officers on Power Safety.	-Do-